

# TEST REPORT

**Client** : Acclaim Lighting LLC  
**Address** : 6122 S Eastern Ave Los Angeles CA 90040 USA

**The following sample(s) and sample information was/were submitted and identified by/on the behalf of the client:**

Sample Name : Lighting Fixture  
Sample Type : Dyna Drum SO  
Sample Quantity : 1pc  
Sample Received Date : Aug. 10, 2017  
Sample tested Date : Aug. 11, 2017

Tested by

*Cifer. Lu*

Cifer Lu(Lu Jiang)

Aug. 11, 2017

Reviewed by

*Kyle*

Kyle Xiong(Xiong Zhi)

Aug. 11, 2017

Approved by

*Taylor. Chen*

Taylor Chen(Chen Meng)  
Authorized Officer

Aug. 11, 2017

Attestation of Global Compliance (Shenzhen) Co., Ltd.

## CAUTION:

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of AGC, this report can't be reproduced except in full.



The results shown in this test report refer only to the sample(s) tested unless otherwise stated and the sample(s) are retained for 30 days only. The document is issued by AGC, this document cannot be reproduced except in full with our prior written permission. The document is available on request and the brief information for its validation can be assessable and confirmed at <http://www.agc-cert.com>

# TEST REPORT

## Test Item: IK07 test

### 1) Environment conditions:

Temperature: 23.6°C Humidity: 52%RH

### 2) Tested Sample:

Sample No.	Sample Name	Sample Type	Sample Quantity
001	Lighting Fixture	Dyna Drum SO	1pc

### 3) Reference Basis: IEC 62262:2002

### 4) Test Condition:

- Collision energy: 2J;
- The impact is uniformly distributed on the tested surface of the sample, and the impact number of the same location is not more than three times;
- Number of impacts: 5.

### 5) Test Equipment:

Sequence	Equipment Name	Serial No.	Valid Date to
1	Vertical impact test device	AGC-RE-E092	Jul. 26, 2018

### 6) Test Results:

Sample No.	Test result	Conclusion
001	After the test, the shell of the sample was not damaged.	Pass

### Sample Photo before the Test:



The results shown in this test report refer only to the sample(s) tested unless otherwise stated and the sample(s) are retained for 30 days only. The document is issued by AGC; this document cannot be reproduced except in full with our prior written permission. The document is available on request and the brief information for its validation can be assessable and confirmed at <http://www.agc-cert.com>



# TEST REPORT

## Sample Photo during the Test:



## Sample Photo after the Test:



\*\*\* End of Report \*\*\*

Testing laboratory address: 1F., Building C West, Qinyu Industrial Park, Nanchang Community, Baoan Road, Xixiang Street, Baoan District, Shenzhen, China.

## CAUTION:

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of AGC, this report can't be reproduced except in full.

The results shown in this test report refer only to the sample(s) tested unless otherwise stated and the sample(s) are retained for 30 days only. The document is issued by AGC, this document cannot be reproduced except in full with our prior written permission. The document is available on request and the brief information for its validation can be assessable and confirmed at <http://www.agc-cert.com>